CZCKHI500DA488VAA223RNA964
OO [redacted]
DE [redacted] 16 1622009
ZKZK OO NSD NRL DE
O 092010Z ZYH
FM [redacted]
TO DIRNAVSECGRUEUR
CINCUSNAVEUR
DIRNAVSECGRU
ASSTDIRNAVSECGRU
ZEM

P.L. 86-36

1967 JUN 10 00 59 [redacted]

EO 1.4.(c)

377

~~S E C R E T COMINT CHANNELS~~
USS LIBERTY PHYSICAL SECURITY
A. CTF SIX ZERO 091334Z (PASEP)
B. CTG SIX ZERO PT FIVE 091406Z (PASEP)
C. CTF SIX ZERO 091726Z (PASEP)
D. DIRNAVSECGRU 091456Z
1. REFS A THRU C OUTLINE IMMEDIATE STEPS TAKEN TO PROTECT CLASSIFIED MATERIAL ABOARD LIBERTY. OTHER STEPS TAKEN ARE:
A. ONE DD SENT TO SEARCH BACKDOWN TRACK UNTIL DARKNESS.
B. A COLLISION MAT AND MATTRESSES ARE BEING PLACED OVER HOLE TO CONTROL FURTHER LOSS OF MATERIAL.
2. USN 855 COMMUNICATION SPACES, OPERATIONS CONTROL, AND SURROUNDING SPACES VIRTUALLY DESTROYED BY EXPLOSION. DAMAGE CONTROL PERS WERE UNABLE TO GAIN ACCESS TO AREA OF HOLE UNTIL ABOUT 091600Z DUE TO FLOODING. SHIP NOW LISTING ONLY ABOUT FIVE DEGREES AND SHORING CAN TAKE PLACE.
3. GOOD POSSIBILITY THAT MOST DEBRIS FLOATING OUT OF HOLE MAY BE FROM GSK STOREROOM LOCATED BELOW RESEARCH OPERATIONS SPACES.
150

ACT: G531....

INFO: G...GB...G1...G20...G30...G50...G51...G52...FOLDERS...

Declassified and approved for release by NSA and the U.S. Navy on 01-30-2007 pursuant to E.O. 12958, as amended, ST 51666